Camas Creek Subbasin Assessment and Total Maximum Daily Load





Department of Environmental Quality

Final, August 2005


Camas Creek Subbasin Assessment and TMDL

Final, August 2005

Prepared by:
Jennifer Claire
Twin Falls Regional Office
Department of Environmental Quality
601 Pole Line Road, Suite #2
Twin Falls, Idaho 83301

Acknowledgments

Samples for the Camas Creek Subbasin Assessment and Total Maximum Daily Load were collected by Jennifer Claire and environmental consulting firms. Reservoir data were collected by Clyde Lay and Jennifer Claire. Habitat data were collected by Jennifer Claire, Alan Monek, Clyde Lay, and Sean Woodhead. ArcView figures were compiled by Rob Sharpnack. Clyde Lay and Sonny Buhidar reviewed the document throughout the process. Sean Woodhead and many of the Beneficial Use Reconnaissance Program crews collected the biological data. Mark Shumar provided aerial interpretation of canopy cover for temperature TMDLs. Dennis Meier provided technical editing suggestions for the document. The Wood River Watershed Advisory Group (WAG) provided public feedback and input throughout the process. Cover photo of Camas Prairie at Johnson Hill overlook taken by Jennifer Claire.



August 2005

Table of Contents

Acknowledgments	
Table of Contents	iii
List of Tables	ix
List of Figures	xii
List of Appendices	xiv
Abbreviations, Acronyms, and Symbols	xv
Executive Summary	
Subbasin at a Glance	xvii
Key Findings	
Conclusions Drawn from Analysis of Biological Data	
Conclusions Drawn from Analysis of pH, DO, and Turbidity	xxiv
Conclusions Drawn from Analysis of Temperature Data	
Conclusions Drawn from Analysis of E. coli Data	xxv
Conclusions Drawn from Analysis of Sediment Data	
Conclusions Drawn from the Analysis of Nutrient Data	
1. Subbasin Assessment – Watershed Characterization	
1.1 Introduction	
Background	
Idaho's Role	2
1.2 Physical and Biological Characteristics	3
Climate	
Precipitation	
Air Temperature and Available Sunlight	
Snow Depth and Snowfall	
Evaporation and Wind Erosion	
Subbasin Characteristics	
Hydrography	5
Geology and/or soils	
Topography	
Vegetation	
Biological Communities	
Water Chemistry	
Subwatershed Characteristics	
5 th field Hydrologic Unit Code (HUC)	
Watershed Area	
1.3 Cultural Characteristics	
Land Use	
Land Ownership, Cultural Features, and Population	
History and Economics	30
2. Subbasin Assessment – Water Quality Concerns and Status	
2.1 Water Quality Limited Segments Occurring in the Subbasin	
About Assessment Units	
Listed Waters	
2.2 Applicable Water Quality Standards	36

	Beneficial Uses	36
	Existing Uses	36
	Designated Uses	
	Presumed Uses	36
	Surface Water Quality Criteria	
2.3	Pollutant/Beneficial Use Support Status Relationships	
	Temperature	
	Dissolved Oxygen	
	Sediment	
	Bacteria	
	Nutrients	
	Sediment – Nutrient Relationship	
	Floating, Suspended, or Submerged Matter (Nuisance Algae)	
2 4	Summary and Analysis of Existing Water Quality Data	
۷.7	Analysis Process	
	Bioassessment Data	
	Hydrology Water Chemistry	40
	Numerical Criteria	
	Narrative Criteria	
	Nutrient Criteria	
	Sediment Criteria	
	Water Quality Assessments of Listed Water Bodies	
	Soldier Creek	52
	Biological and Other Data	
	Hydrology	
	Water Column Data	
	Conclusions	
	Willow Creek	
	Biological and Other Data	
	Hydrology	
	Water Column Data	
	Conclusions	
	Beaver Creek	
	Biological and Other Data	
	Hydrology	
	Water Column Data	
	Conclusions	83
	Little Beaver Creek	84
	Biological and Other Data	84
	Hydrology	86
	Water Column Data	
	Conclusions	91
	Camp Creek	
	Biological and Other Data	
	Hydrology	

Water Column Data	
Conclusions	100
Elk Creek	101
Biological and Other Data	102
Hydrology	103
Water Column Data	
Conclusions	108
Corral Creek	109
Biological and Other Data	110
Hydrology	
Water Column Data	
Conclusions	
Cow Creek	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
Wild Horse Creek	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
McKinney Creek	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
Dairy Creek	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
Camas Creek	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
Mormon Reservoir	
Biological and Other Data	
Hydrology	
Water Column Data	
Conclusions	
2.5 Data Gaps	_
3. Subbasin Assessment – Pollutant Source Inventory	159
3.1 Point Sources	
3.2 Nonpoint Sources	

4. Subbasin Assessment – Summary of Past and P	161
5. Total Maximum Daily Loads	
5.1 TMDL Components	
Soldier Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Reasonable Assurance	
Willow Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Beaver Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Little Beaver Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Camp Creek	
Design Conditions	
Target Selection	170
Load Capacity	
Estimates of Existing Pollutant Loads Load Allocation	
Reasonable Assurance	
Elk Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	

Estimates of Existing Pollutant Loads	
Load Allocation	181
Reasonable Assurance	182
Corral Creek	182
Design Conditions	183
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Reasonable Assurance	
Cow Creek above the Reservoir	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Reasonable Assurance	
Wild Horse Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Reasonable Assurance	
McKinney Creek	
Design Conditions	
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load AllocationReasonable Assurance	
Dairy Creek Design Conditions	19 <i>1</i> 107
Target Selection	
Monitoring Points	
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	199
Reasonable Assurance	
Camas Creek	
Design Conditions	201 202
LALDEL SEIECTION	/(!/

Monitoring Points	202
Load Capacity	
Estimates of Existing Pollutant Loads	
Load Allocation	
Reasonable Assurance	205
Construction Storm Water and TMDL Wasteload Allocations	205
Construction Storm Water	205
The Construction General Permit (CGP)	206
Storm Water Pollution Prevention Plan (SWPPP)	
Construction Storm Water Requirements	
Future Growth Potential	
5.2 Implementation Strategies	
5.3 Conclusions	
References Cited	
Geographic Information System (GIS) Coverages	

List of Tables

Table 1.	Impaired waters of the Camas Creek Subbasin	xix
Table 2.	Streams and pollutants for which TMDLs were developed	xxi
Table 3.	Summary of assessment outcomes	
Table 4.	Average precipitation (inches) in the Camas Creek Subbasin	4
Table 5.	Camas Creek Subbasin air temperature	4
Table 6.	Geologic formations of the Camas Creek Subbasin	8
Table 7.	Fisheries of the Camas Creek Subbasin	. 14
	Assessment units of the subbasin and their beneficial use status.	
	Camas Creek Subbasin 5th field HUC watershed areas	
	Camas Creek Subbasin watershed attributes	
Table 11.	Land use of the Camas Creek Subbasin	. 24
Table 12.	Land ownership in the Camas Creek Subbasin	. 26
	Agricultural statistics in the counties of Camas Creek Subbasin	
	Point source facilities of the Camas Creek Subbasin	
	§303(d) segments in the Camas Creek Subbasin	
	Camas Creek Subbasin designated beneficial uses	
	Camas Creek Subbasin existing/presumed beneficial uses	
	Characteristics of Soldier Creek	
	Soldier Creek fish data	
	Soldier Creek water chemistry data	
	Soldier Creek temperature elevations	
	Soldier Creek canopy cover	
	Characteristics of Willow Creek	
	Condition rating scores for Willow Creek	
	Willow Creek fish data	
	Willow Creek water chemistry data	
	Willow Creek temperature elevations.	
	Willow Creek canopy cover	
	Characteristics of Beaver Creek	
	Condition rating scores for Beaver Creek	
	Beaver Creek fish data	
	Beaver Creek water chemistry data	
	Beaver Creek temperature elevations	
Table 34.	Beaver Creek canopy cover	. 83
	Characteristics of Little Beaver Creek	
	Condition rating scores for Little Beaver Creek	
	Little Beaver Creek fish data	
	Little Beaver Creek water chemistry data	
	Little Beaver Creek temperature elevations	
	Little Beaver Creek canopy cover	
	Characteristics of Camp Creek.	
	Camp Creek fish data	
	Camp Creek water chemistry data	
	Camp Creek temperature elevations	
Table 45.	Camp Creek canopy cover	100

Table 46.	Characteristics of Elk Creek1	103
Table 47.	Elk Creek water chemistry data1	106
Table 48.	Corral Creek fish data1	110
Table 49.	Corral Creek water chemistry data1	113
Table 50.	Corral Creek temperature elevations1	115
Table 51.	Corral Creek canopy cover1	117
Table 52.	Cow Creek water chemistry data1	121
Table 53.	Wild Horse Creek fish data1	125
Table 54.	Wild Horse Creek water chemistry data1	128
Table 55.	Wild Horse Creek temperature elevations1	130
	Wild Horse Creek canopy cover1	
Table 57.	Condition rating scores for McKinney Creek	133
Table 58.	McKinney Creek fish data1	134
Table 59.	McKinney Creek water chemistry data1	136
	Dairy Creek water chemistry data1	
	Characteristics of Camas Creek1	
Table 62.	Condition rating scores for Camas Creek	146
	Camas Creek fish data1	
Table 64.	Camas Creek water chemistry data1	150
	Camas Creek elevated temperatures1	
	Camas Creek canopy cover1	
Table 67.	Point sources in the Camas Creek Subbasin1	159
Table 68.	Nonpoint sources of Camas Creek Subbasin	160
Table 69.	Camas Creek subbasin pollution control efforts1	161
	Soldier Creek load reductions1	
Table 71.	Soldier Creek load allocations1	169
Table 72.	Soldier Creek stream bank erosion values1	169
	City of Fairfield allowable effluent temperatures1	
	Willow Creek load reductions1	
Table 75.	Willow Creek load allocations1	172
	Beaver Creek load reductions1	
Table 77.	Beaver Creek load allocations1	174
Table 78.	Little Beaver Creek load reductions1	175
Table 79.	Little Beaver Creek load allocations1	176
Table 80.	Camp Creek load reductions1	179
	Camp Creek load allocations1	
Table 82.	Camp Creek stream bank erosion values1	179
	Elk Creek load reductions1	
Table 84.	Elk Creek load allocations1	182
Table 85.	Elk Creek stream bank erosion values1	182
Table 86.	Corral Creek load reductions1	185
Table 87.	Corral Creek load allocations1	185
	Corral Creek stream bank erosion values1	
	Cow Creek load reductions1	
	Cow Creek load allocations	
	Cow Creek stream bank erosion values	

Table 92. Wild Horse Creek load reductions	193
Table 93. Wild Horse Creek load allocations	193
Table 94. Wild Horse Creek stream bank erosion values	194
Table 95. McKinney Creek load reductions	196
Table 96. McKinney Creek load allocations	196
Table 97. McKinney Creek stream bank erosion values	197
Table 98. Dairy Creek load reductions	200
Table 99. Dairy Creek load allocations	200
Table 100. Dairy Creek stream erosion values	200
Table 101. Camas Creek load reductions	204
Table 102. Camas Creek load allocations	
Table 103. Camas Creek stream erosion values	205
Table 104. Summary of assessment criteria results	208
Table 105. Summary of assessment outcomes	209
Table 106. Flow alteration impacting water quality	210
Table 107. Metric - English unit conversions	235
Table 108. Endangered, threatened and sensitive species	236
Table 109. Surface water quality criteria	238
Table 110. Stream bank erosion segmentation identification	241
Table 111. Canopy cover estimates and targets	
Table 112. Aerial versus pathfinder data	254
Table 113 Data sources for Camas Creek Subbasin assessment	265

List of Figures

Figure 1.	Subbasin at a glance	xviii
	Impaired water bodies of the Camas Subbasin	
_	Camas Creek Subbasin average hydrology	
_	Dams and gauging stations in the Camas Creek Subbasin	
	Geologic formations of the Camas Creek Subbasin	
	Soil erosivity (K factors) of the Camas Creek Subbasin	
	Vegetation coverage of the Camas Creek Subbasin	
	Average annual TSS (mg/L) in the subbasin	
_	Average annual TP (mg/L) in the subbasin	
_	. Average annual <i>E. coli</i> in the subbasin	
	. 5th field HUCs for Camas Creek Subbasin	
	. Land use of Camas Creek Subbasin	
	. Land ownership of the Camas Creek Subbasin	
	. Counties of the Camas Creek Subbasin	
	. Cities of the Camas Creek Subbasin	
	. Point source facilities in the Camas Creek Subbasin	
	. 303(d) listed streams in Camas Creek Subbasin	
Figure 18	. Bedload sediment in streams meeting beneficial uses	52
	. Soldier Creek flow (cfs) regression analysis	
	. Soldier Creek predicted hydrograph	
Figure 21	. Soldier Creek SS temperatures (2003)	61
	. Willow Creek flow (cfs) regression analysis	
_	. Willow Creek predicted hydrograph	
Figure 24	. Willow Creek SS temperatures (2002)	72
	. Beaver Creek flow (cfs) regression analysis	
	. Beaver Creek predicted hydrograph	
Figure 27	. Beaver Creek SS temperatures (2003)	82
Figure 28	. Little Beaver Creek flow (cfs) regression analysis	87
Figure 29	. Little Beaver Creek predicted hydrograph	87
Figure 30	. Little Beaver Creek CWAL temperatures (2002)	90
Figure 31	. Camp Creek actual hydrograph in drought years (1977, 2001-200	3).
		95
Figure 32	. Camp Creek CWAL temperatures (2003)	99
Figure 33	. Elk Creek flow (cfs) regression analysis	104
	. Elk Creek predicted hydrograph	
Figure 35	. Comparison of TP (mg/L) and TIN (mg/L) values	107
	. Corral Creek flow (cfs) regression analysis	
Figure 37	. Corral Creek predicted hydrograph	112
Figure 38	. Corral Creek (upper) CWAL temperatures (2003)	116
	. Cow Creek (above the reservoir) flow (cfs) regression analysis	
	. Cow Creek (above the reservoir) predicted hydrograph	
	. Wild Horse Creek flow (cfs) regression analysis	
	. Wild Horse Creek predicted hydrograph	
Figure 43	Wild Horse Creek CWAL temperatures (2003)	130

Figure 44. McKinney Creek flow (cfs) regression analysis	135
Figure 45. McKinney Creek predicted hydrograph	135
Figure 46. Dairy Creek flow (cfs) regression analysis	140
Figure 47. Dairy Creek predicted hydrograph	141
Figure 48. Camas Creek annual hydrograph	
Figure 49. Camas Creek in spring runoff	
Figure 50. Camas Creek CWAL temperatures (Lower-2002)	
Figure 51. Camas Creek Subbasin stream bank erosion segmentation	

List of Appendices

Annondiv 1	Unit Conversion Chart	225
• •		
Appendix 2.	Endangered, Threatened, and Sensitive Species	236
Appendix 3.	State and Site-Specific Standards and Criteria	238
Appendix 4.	Stream bank erosion inventory segments	241
Appendix 5.	Canopy Cover Estimates and Targets	250
	Implementation Strategies	
• •	Data Sources	
• •	Distribution List	
• •	Public Comments	

Abbreviations, Acronyms, and Symbols

§303(d)	Refers to section 303 subsection (d) of the Clean Western Act, and list of improved	DEQ	Department of Environmental Quality
	Water Act, or a list of impaired water bodies required by this section	DO	dissolved oxygen
μ	micro, one-one thousandth	DWS	domestic water supply
§	Section (usually a section of	EPA	United States Environmental Protection Agency
	federal or state rules or statutes)	F	Fahrenheit
ADB	assessment database	GIS	Geographical Information Systems
AU	assessment unit	HUC	Hydrologic Unit Code
AWS	agricultural water supply	IDAPA	Refers to citations of Idaho
BLM	United States Bureau of Land Management	IDFG	administrative rules Idaho Department of Fish and
BMP	Best Management Practice	IDFG	Game
BOD	biochemical oxygen demand	IDWR	Idaho Department of Water Resources
BURP	Beneficial Use Reconnaissance Program	km	kilometer
C	Celsius	km ²	square kilometer
CFR	Code of Federal Regulations (refers to citations in the	kWh/day	kilowatt hours per day
	federal administrative rules)	LA	load allocation
cfs	cubic feet per second	LC	load capacity
cfu	colony forming units	m	meter
cm	centimeters	m ³	cubic meter
CWA	Clean Water Act	mi	mile
CWAL	cold water aquatic life	mi ²	square miles

mg/L	milligrams per liter		
mm	millimeter	SS	salmonid spawning
111111	minimeter	TIN	total inorganic nitrogen
MOS	margin of safety	TMDL	total maximum daily load
n.a.	not applicable	INIDL	total maximum daily load
NIA	# 04 000000 d	TP	total phosphorus
NA	not assessed	TSS	total suspended solids
NB	natural background	4.1	-
NPDES	National Pollutant Discharge	t/yr	tons per year
	Elimination System	U.S.	United States
NRCS	Natural Resources	U.S.C.	United States Code
	Conservation Service		
NTU	nephlometric turbidity unit	USDA	United States Department of Agriculture
PCR	primary contact recreation	USFS	United States Forest Service
ppm	part(s) per million	USGS	United States Geological Survey
SBA	subbasin assessment		·
SCR	secondary contact recreation	WAG	Watershed Advisory Group
BCK	secondary contact recreation	WBAG	Waterbody Assessment
SFI	DEQ's stream fish index		Guidance
SHI	DEQ's stream habitat index	WLA	wasteload allocation
SMI	DEQ's stream macroinvertebrate index		

Executive Summary

The federal *Clean Water Act* (CWA) requires that states and tribes restore and maintain the chemical, physical, and biological integrity of the nation's waters. States and tribes, pursuant to Section 303 of the CWA are to adopt water quality standards necessary to protect fish, shellfish, and wildlife while providing for recreation in and on the waters whenever possible. Section 303(d) of the CWA establishes requirements for states and tribes to identify and prioritize water bodies that are water quality limited (i.e., water bodies that do not meet water quality standards). States and tribes must periodically publish a priority list of impaired waters, currently every two years. For waters identified on this list, states and tribes must develop a *total maximum daily load* (TMDL) for the pollutants, set at a level to achieve water quality standards. This document addresses the water bodies in the Camas Creek Subbasin that have been placed on what is known as the "§303(d) list."

This subbasin assessment and TMDL analysis has been developed to comply with Idaho's TMDL schedule. This assessment describes the physical, biological, and cultural setting; water quality status; pollutant sources; and recent pollution control actions in the Camas Creek Subbasin located in south central Idaho. The first part of this document, the subbasin assessment, is an important first step in leading to the TMDL. The starting point for this assessment was Idaho's current §303(d) list of water quality limited water bodies. Twelve segments of the Camas Creek Subbasin were listed on this list. The subbasin assessment portion of this document examines the current status of §303(d) listed waters, and defines the extent of impairment and causes of water quality limitation throughout the subbasin. The loading analysis quantifies pollutant sources and allocates responsibility for load reductions needed to return listed waters to a condition of meeting water quality standards.

Subbasin at a Glance

The Camas Subbasin lies in south central Idaho (Figure 1). Camas Creek is the main water body that drains the subbasin. The headwaters of the creek originate in the flat Camas Prairie, flow through the Camas Prairie, and then discharge into Magic Reservoir. There are two ecoregions within the subbasin: the headwaters of the tributaries that feed into Camas Creek from the north originate in the Northern Rockies, while the remainder of the subbasin lies in the Snake River Plain/high deserts. Transitional zones exist between the two ecoregions.




Figure 1. Subbasin at a glance.

Hydrologically there is a great deal of activity occurring within the subbasin:

- Snow runoff events in the spring months feed the water bodies. These runoff events are large and rapid as the majority of the tributaries drain south facing slopes.
- Ground water is likely to play an important role in maintaining perennial flows, as the majority of the subbasin lies over the Camas Prairie aquifer.
- Water in the creek is more likely to continue as surface flow if water tables are higher and prevent the surface water from dissipating into the ground.
- The land uses of the subbasin require the diversion of water from their natural channels and in the past have led to the straightening of many channels.
- Many of the perennial water bodies in the subbasin have segments that act more as intermittent streams.

Hydrology is the most important factor contributing to impacts in the water bodies of the Camas Creek Subbasin.

The land of the subbasin is used in a number of ways by a number of entities:

- The largest land use coverage within the subbasin is rangeland followed by dry land agriculture.
- The largest land ownership coverage within the subbasin is private land followed by federally managed public lands.
- The largest vegetation coverage within the subbasin is shrub land followed by agricultural land.
- Most activity within the subbasin is nonpoint source activity.
- The City of Fairfield discharges its wastewater to a ditch that discharges to Soldier Creek.

In 1998, twelve water body segments of the Camas Creek Subbasin were identified as being impaired (Table 1 and Figure 2). Many of these water bodies have been identified within the 1998 303(d) list as being impaired by unknown pollutants; a couple have been identified as being impaired by bacteria, dissolved oxygen, nutrients, sediment, and flow alteration. The beneficial uses that were being impacted by pollutants were cold water aquatic life, salmonid spawning, primary contact recreation, and secondary contact recreation.

Table 1. Impaired waters of the Camas Creek Subbasin.


Water body Name	Assessment Unit	1998 §303(d) Boundaries	Pollutants
Camas Creek	ID17040220SK013_05 ID17040220SK001_05 ID17040220SK007_05 ID17040220SK018_04 ID17040220SK018_03 ID17040220SK018_02	Headwaters to Macon Flat Bridge	SED
Soldier Creek	ID17040220SK011_02	Baseline to Camas Creek	BAC, DO, NUT, QALT, SED
Mormon Reservoir	ID17040220SK023L_0L		BAC, DO, NUT, QALT, SED
Little Beaver Creek	ID17040220SK004_02	Headwaters to Beaver Creek	UNKN
Camp Creek	ID17040220SK002_02 ID17040220SK002_03	Headwater to Camas Creek	UNKN
Willow Creek	ID17040220SK003_04	Beaver Creek to Camas Creek	UNKN
Elk Creek	ID17040220SK006_02	Baseline Road to Camas Creek	UNKN
McKinney Creek	ID17040220SK025_02	Headwaters to Mormon Reservoir	UNKN
Corral Creek	ID17040220SK015_03	Highway 20 to Camas Creek	UNKN
Cow Creek	ID17040220SK018_02	Headwaters to Cow Creek Reservoir	UNKN
Wild Horse Creek	ID17040220SK021_03	Highway 20 to Camas Creek	UNKN
Beaver Creek	ID17040220SK004_02	Headwaters to Willow Creek	UNKN

^aRefers to a list, created in 1998, of water bodies in Idaho that did not fully support at least one beneficial use. This list is required under section 303, subsection "d," of the Clean Water Act.

Through the subbasin assessment, it has been identified which pollutants are impacting the beneficial uses of the listed water bodies in the Camas Creek Subbasin. These findings will be discussed in the following section.

^bSED-sediment, BAC-bacteria, DO-dissolved oxygen, NUT-nutrients, QALT-flow alteration, UNKN-unknown.

Camas Creek Subbasin 1998 303(d) Listed Waterbodies



N	1998 Water Quality Limited Waterbodies
	Lakes and Reserviors
Δ	Major Streams and Rivers
	Camas Creek Subbasin

Mamb e r	Name	Miles
1	Beaver Creek	5.9800
2	Camas Creek	51.3200
3	Camp Creek	12.6500
4	Corral Creek	3.9800
5	Cow Creek	2.9100
6	Elk Creek	2.4600
7	Little Beaver Creek	4.3400
В	McKinney Creek	10.1100
9	Mormon Reservoir	0.0000
10	Soldier Creek	6.7000
11	Wild Horse Creek	2.7100
12	Willow Creek	9.0400

repared by Rob Sharpnack - October 2000

Figure 2. Impaired water bodies of the Camas Subbasin.

Key Findings

Data of various types were used to identify whether beneficial uses were fully supported in the 303(d) listed water bodies of the Camas Creek Subbasin:

- Biological data, including fish, macroinvertebrate, and habitat data.
- Water chemistry data, including pH, dissolved oxygen (DO), and turbidity
- Water chemistry data for nutrients, including total phosphorous (TP), total inorganic nitrogen (TIN), and chlorophyll.
- Water chemistry data and habitat data for sediment including total suspended solids (TSS), percent fines, and stream bank erosion inventories.
- Water chemistry data and habitat data for temperature including daily maximum and daily average temperatures and canopy cover.
- Water chemistry data for bacteria including Escherichia coli (E. coli) data.

These data were analyzed as described in Section 2 of this document and conclusions were drawn from the findings. Table 2 shows those water bodies requiring TMDLs. Table 2 summarizes the findings for each water body that was analyzed.

Table 2. Streams and pollutants for which TMDLs were developed.

Stream	tream Pollutant(s)	
Camp Creek	Sediment, Temperature	
Elk Creek	Sediment,	
Soldier Creek	Sediment, Temperature	
Corral Creek	Sediment, Temperature	
Cow Creek	Sediment, Nutrients	
Wild Horse Creek	Sediment, Bacteria, Temperature	
Dairy Creek	Sediment, Nutrients	
McKinney Creek	Sediment	
Camas Creek	Sediment, Nutrients, Temperature	
Mormon Reservoir	See Dairy and McKinney Creek	

Table 3. Summary of assessment outcomes.

Water body Segment	Assessment Unit	Pollutant	TMDL Done	Recommended Changes to §303(d) List	Justification
Camas Creek	ID17040220SK013_05 ID17040220SK001_05 ID17040220SK007_05 ID17040220SK018_04 ID17040220SK018_03 ID17040220SK018_02	SED, TEMP, NUT	Yes	Add TEMP, NUT, and QALT,	Not meeting standards, delivery to storage system, channelization and diversion
Soldier Creek	ID17040220SK011_02	SED, TEMP	Yes	Remove DO, BACT, NUT Add TEMP	Meeting standards or criteria, Not meeting standards
Mormon Reservoir	ID17040220SK023L_0L	SED, TEMP	Yes	Remove BAC	Meeting standards
Little Beaver Creek	ID17040220SK004_02	TEMP	Yes	Add TEMP	Not meeting standards
Camp Creek	ID17040220SK002_02 ID17040220SK002_03	SED, TEMP	Yes	Remove UNK, Add SED, TEMP, QALT	Not meeting standards or criteria, channelization and storage
Willow Creek	ID17040220SK003_04	TEMP	Yes	Remove UNK, Add TEMP	Not meeting standards
Elk Creek	ID17040220SK006_02	SED	Yes	Remove UNK, Add SED	Not meeting criteria
McKinney Creek	ID17040220SK025_02	SED	Yes	Remove UNK, Add SED	Not meeting criteria
Corral Creek	ID17040220SK015_03	SED, TEMP	Yes	Remove UNK, Add SED, TEMP	Not meeting criteria or standards
Cow Creek	ID17040220SK018_02	SED, NUT	Yes	Remove UNK, Add SED, NUT	Delivering to storage system, not meeting criteria
Wild Horse Creek	ID17040220SK021_03	SED, BACT, TEMP	Yes	Remove UNK, Add SED, BACT, TEMP	Not meeting criteria or standards
Beaver Creek	ID17040220SK004_02	TEMP	Yes	Remove UNK, Add TEMP	Not meeting standards
Dairy Creek	ID17040220SK024_02	SED, NUT	Yes	Add SED, NUT	Delivering to storage system, not meeting criteria

^a1998 303(d) refers to a list created in 1998 of water bodies in Idaho that did not fully support at least one beneficial use. This list is required under section 303 subsection "d" of the Clean Water Act.

^bAU- assessment unit (assessment unit prefix to values in table is Id17040221), SED- sediment, NUT- nutrient, BAC- bacteria, TEMP- temperature, DO- dissolved oxygen, QALT- flow alteration, UNK-Unknown.

c303(d) listed segments will remain the same; however TMDLs are completed on the entire length of the creek.

Total Maximum Daily Loads have been completed on all of the listed segments:

- Nutrient TMDLs have been completed on Cow Creek, Dairy Creek, and Camas Creek to aid in protecting water quality of the receiving reservoirs.
- Stream bank erosion TMDLs for sediment have been completed on Camp Creek, Elk Creek, Soldier Creek, Corral Creek, Wild Horse Creek, Cow Creek, Camas Creek, Dairy Creek, and McKinney Creek.
- A bacteria TMDL has been completed on Wild Horse Creek.
- Canopy cover TMDLs for temperature elevations have been completed on Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Soldier Creek, Corral Creek, Wild Horse Creek, and Camas Creek.
- Nutrient and/or sediment TMDLs on McKinney Creek and Dairy Creek have been completed to aid in improving the water quality of Mormon Reservoir.
- Flow alteration or lack of flow has been identified as pollution for many of the water bodies, although TMDLs are not developed for flow alteration. Water bodies listed as impacted by flow alteration include Camp Creek, Elk Creek, Soldier Creek, Corral Creek, Wild Horse Creek, Dairy Creek, Camas Creek, McKinney Creek, and Mormon Reservoir. The flow on these creeks during summer months is minimal; water usage and ground water pumping likely contributes to their dry state.
- Three of the water bodies (Willow Creek, Beaver Creek, and Little Beaver Creek) that were listed on the 303(d) list had sufficient biological data indicating that beneficial uses were fully supported. Sediment TMDLs were not completed on them as beneficial uses are fully supported. However, temperature TMDLs were completed on them as their temperature data (a numeric standard) indicates that water quality was not capable of fully supporting beneficial uses.

More detailed discussions of the data analyses are presented in the following.

Conclusions Drawn from Analysis of Biological Data

Conclusions made in relation to biological data and aquatic life beneficial uses support status for Camas Creek Subbasin are as follows:

- Biological data indicates that aquatic life beneficial uses of Willow Creek, Beaver Creek, and Little Beaver Creek are fully supported.
- Biological data indicates that aquatic life beneficial uses of McKinney Creek are not fully supported.
- Biological data on Soldier Creek, Camp Creek, and Corral Creek were not assessed because sites were located on intermittent reaches of the water bodies. There is a biological data gap on perennial segments of these water bodies.
- Biological data on Cow Creek was not assessed because the upper portion of this water body is not consistently perennial.

- Biological data on Wild Horse Creek was not assessed because the water body is an intermittent water body although there are a series of perennial beaver dam pools.
- Biological data has not been collected on Dairy Creek and should not be used to assess beneficial uses as it is an intermittent water body.
- Biological data collected on intermittent reaches of Camas Creek were not assessed, but biological data on the perennial reaches of Camas Creek indicate aquatic life beneficial uses are not fully supported.

Conclusions Drawn from Analysis of pH, DO, and Turbidity

Conclusions made in relation to water chemistry data (pH, DO, and turbidity) are as follows:

- Water chemistry data (pH, DO, and turbidity) indicated that water quality was sufficient to support beneficial uses in Soldier Creek, Willow Creek, Beaver Creek, Camp Creek, Corral Creek, Cow Creek, Wild Horse Creek, McKinney Creek, and Dairy Creek.
- Water chemistry data (pH, DO, and turbidity) were data gaps in Little Beaver Creek due to site inaccessibility and drought conditions.
- Water chemistry data (DO) indicated that water quality was not sufficient to support beneficial uses in Camas Creek.

Conclusions Drawn from Analysis of Temperature Data

Conclusions made in relation to water temperature for Cold Water Aquatic Life Uses (CWAL) and Salmonid Spawning (SS) critical periods are as follows:

- Maximum daily temperature data was elevated more than 10% of the time for CWAL critical periods on Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Corral Creek, Wild Horse Creek, and Camas Creek.
- Average daily temperature data was elevated more than 10% of the time for CWAL critical periods on Camp Creek, Wild Horse Creek, and Camas Creek.
- Maximum and average daily temperature data was elevated more than 10% of the time for SS critical periods on Soldier Creek, Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Corral Creek, and Camas Creek.
- Temperature data is a data gap for CWAL critical periods on a number of creeks due to the lack of water in the stream, these creeks include Soldier Creek, Elk Creek, Cow Creek, McKinney Creek, and Dairy Creek.
- A number of factors likely contribute to these temperature elevations, including canopy cover deficiencies resulting from land management practices, beaver dam complexes, geologic formations—such as basalt canyons that retain heat and may inhibit sufficient riparian development—flow alteration, ground water influences, and desert conditions of south central Idaho.

Conclusions Drawn from Analysis of E. coli Data

Conclusions made in relation to support status of the contact recreation beneficial uses based on analysis of *E. coli* data are as follows:

- Primary Contact Recreation beneficial uses are fully supported (< 406 cfu/100ml of *E. coli*)on Soldier Creek, Willow Creek, and Camas Creek.
- Secondary Contact Recreation beneficial uses are fully supported (<576 cfu/100ml of *E. coli*) on Beaver Creek, Little Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Cow Creek, McKinney Creek, and Dairy Creek.
- Secondary Contact Recreation beneficial uses are not fully supported (>576 cfu/100 ml of *E. coli*) on Wild Horse Creek. Follow up samples also yielded geometric mean values (> 126 cfu/100ml of *E. coli*) that confirmed the elevation of *E. coli*.

Conclusions Drawn from Analysis of Sediment Data

Conclusions made in relation to the impact of sediment as a pollutant on aquatic life beneficial uses are as follows:

- The average annual TSS values and daily maximum TSS values were not elevated above assessment criteria on Soldier Creek, Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Cow Creek, Wild Horse Creek, McKinney Creek, Dairy Creek, and Camas Creek.
- Percent fines data was elevated above assessment criteria on Soldier Creek, Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Cow Creek, Wild Horse Creek, McKinney Creek, Dairy Creek, and Camas Creek.
- Stream bank inventories indicate that there is an excessive source of sediment coming from the stream banks on Soldier Creek, Willow Creek, Little Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Cow Creek, Wild Horse Creek, McKinney Creek, Dairy Creek, and Camas Creek.
- Stream bank inventories indicate that there is not an excessive source of sediment coming from the stream banks on Beaver Creek.

Conclusions Drawn from the Analysis of Nutrient Data

Conclusions made in relation to the impact of nutrients as a pollutant on the water bodies are as follows:

- Chlorophyll data was not elevated indicating that nuisance aquatic vegetation is not occurring in Soldier Creek, Willow Creek, Beaver Creek, Little Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Cow Creek, Wild Horse Creek, McKinney Creek, Dairy Creek, and Camas Creek.
- Nuisance aquatic vegetation is not going to be a problem on most of these water bodies because there is a distinct lack of water in the water bodies during the growing season.

- Nutrients are not impairing water quality or beneficial uses in Soldier Creek, Willow Creek, Beaver Creek, Camp Creek, Elk Creek, Corral Creek, Wild Horse Creek, McKinney Creek, or Dairy Creek.
- Nutrient data is a data gap on Little Beaver Creek.
- Excessive nutrients (TP values > than the annual average of 0.50 mg/L) are being delivered to the receiving storage waters of Dairy Creek, Camas Creek, and Cow Creek.